APPENDIX A

Roll #168, PTF 85 dated 13 February 1956

LO Camera A-1

- 1. Negatives thin, however only primary processing utilized. Negatives would have been of better quality if secondary development and fix would have been used.
 - 2. Clock image present but unreadable.
 - 3. Pressure striations paralled to film travel and present throughout entire roll.

Roll #191, PTF 98 23 February 1956

RO Camera A-1

1. Clock recorded but illegible.

2. Considerable evidence of flare light, although horizon indicates very little change in a/c atitude.

3. During course of pre-flight check on flight line objects of a classified nature were recorded.

Roll #193, PTF 98 23 February 1956

LO Camera A-1

1. No clock.

2. Marked evidence of unequal tension on rollers and foreign particles on rollers and platen.

NOTE: The vertical photos of PTF 98 were retained at Site for pilot evalution. Our records show however that the vertical camera shutter hung up every 3 or 4 exposures.

Roll 190 and 194, PTF 97 and 98 21 February 1956

Rocker Camera A-1

1. No clock.

2. Negatives dense. May be due in part to reflections from thin layered undercast.

Roll 209, PTF 105 29 February 1956

Rocker Camera A-1. A-25 filter utilized.

Filter Factor 7

- 1. Extremely under exposed.
- 2. Metering trouble.
- 3. No clock.
- 4. Formats askew.